

Version 3.061 31-12-2025

CAN BUS

- Receiveing extended ID messages fixed

Trigger system

- 2JZ VVTi CAM decoder tooth range restored

Other

- 2JZ VVTi added to the trigger wizard
- BMW E46 M54B30 wizard fixed coils assignement

Version 3.060 02-12-2025

Overrun

- Spark cut issue fixed (when overrun was blocked by blip)

Trigger system

- 2JZ VvtI CAM decoder tooth range modified

Windows client

- Password window apperance improved

Version 3.059 12-11-2025

First official release